

6112

F. C. - Causes of Fire

Santa Cruz



Jammer engine, no spark arrestor
on pipe two feet from 500 gal.
tank of oil (Morelli).

8-26-55 M. Pewtherer